6.1.4 TROUBLESHOOTING

Contact the instrument manufacturer if the suggestions on table 6.1-2 fail to resolve the problem.

When using thermistor thermometers:

- ▶ Check the voltage of the batteries.
- ▶ Start with good batteries in instruments and carry spares.

Table 6.1–2.	roubleshooting	guide for	temperature	measurement
--------------	----------------	-----------	-------------	-------------

Symptom	Possible cause and corrective action		
Liquid-in-glass thermometer doesn't read accurately	Check thermometer to see that the liquid is not separated—if separated, take back to the office to reunite column.		
Thermistor thermometer doesn't read accurately	Dirty sensor—remove dirt and oil film.Weak batteries—replace with new batteries.		
Erratic thermistor thermometer readings	 Bad or dirty connection at meter or sensor—tighten or clean connections. Break in the cables—replace cables. Weak batteries—replace with new batteries. 		
Thermistor thermometer slow to stabilize	Dirty sensor—clean sensor to remove dirt and oily film.		